



1826 Kramer Lane, Suite M
Austin, Texas 78758
p | 512-926-6650
f | 512-833-5058
kleinfelder.com

To: Austin Aggregates
Attn.: Mr. Troy Carter
P.O. Box 27935
Austin, Texas 78755

Project: 2009 Austin Aggregates QA


Project No.: 104637
Date: 7-01-09
Control No.: 061608 G

Page 1 of 1

REPORT OF: Sieve Analysis of Fine Aggregates
TEST METHOD: TEX-401A
LAB ID NUMBER: G-2349
MATERIAL DESCRIPTION: 1" Utility Gravel
MATERIAL SOURCE: Plant Stockpile
SAMPLED BY: D. Potteiger, ACI #01147441
DATE RECEIVED: 6-16-09
TEST PERFORMED BY: P. Rajapakse, ACI #01018496
RESULTS:

<u>Sieve Size</u>	<u>Percent Retained</u>	<u>COA Item 510</u>
1 1/2"	0	0
1"	5.0	0-10
1/2"	55.5	40-85
#4	94.6	90-100
#8	99.1	95-100

Report Reviewed by: 


Robert S. Wright, P.E.

The results shown on this report are for the exclusive use of the client for whom they were obtained and apply only to the samples tested and/or inspected. They are not intended to be indicative of the qualities of apparently identical products. The use of our name must receive our prior written approval. Reports must be reproduced in their entirety.